

Program Report

Site Name: Banyan Bay

Generated on: 01/08/2021 03:12:54 PM

Name: Satellite 001

Description:

Communication:

10.94.16.126:50005

Type: LXD - Direct Satellite

Last Sync Time:

01/08/2021 09:55:52 AM

Seasonal Adjust/ET	Daily Seasonal Adjust
Reference	100%
Current Value	100%

	(A) Program A	(B) Program B	(C) Program C	(D) Program D
Watering Day Cycle	Custom S T T	Custom M W S	Custom M W S	Custom S T T
Delay Between Stations				
Program Adjust Method	None	None	None	None
Program Adjust	100%	100%	100%	100%
Max. Program SimulStations	3	3	3	3
Water Window	12:00 AM - 08:00 AM	12:00 AM - 08:00 AM	12:00 AM - 08:00 AM	12:00 AM - 08:00 AM

1	Requested Start	12:01 AM	12:01 AM	12:01 AM	12:01 AM
2	Requested Start	04:00 AM	04:00 AM	04:00 AM	03:30 AM

#	Station Name	Run Time		Run Time		Run Time		Run Time		FZ	Sensor * 1 2 3	Cycle	Soak	Total Adjusted
		Base	Adjusted	Base	Adjusted	Base	Adjusted	Base	Adjusted					
1	N. Side of entry and median	00:10:00	00:10:00							1	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>			00:10:00
2	N. of entry along Kanner Hwy	00:10:00	00:10:00							1	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/>			00:10:00

Program Report

Site Name: Banyan Bay

Generated on: 01/08/2021 03:12:54 PM

Name: Satellite 001

Description:

Communication:

10.94.16.126:50005

Type: LXD - Direct Satellite

Last Sync Time:

01/08/2021 09:55:52 AM

Seasonal Adjust/ET	Daily Seasonal Adjust
Reference	100%
Current Value	100%

#	Station Name	(A) Program A		(B) Program B		(C) Program C		(D) Program D		FZ	Sensor * 1 2 3	Cycle	Soak	Total Adjusted
		Run Time		Run Time		Run Time		Run Time						
		Base	Adjusted	Base	Adjusted	Base	Adjusted	Base	Adjusted					
3	Kanner Hwy and N side of Lake	00:10:00	00:10:00							1	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/>			00:10:00
4	Back of Clubhouse and N of Lake	00:10:00	00:10:00							1	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/>			00:10:00
5	South side and front of Clubhouse	00:10:00	00:10:00							1	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/>			00:10:00
6	Front of clubhouse	00:10:00	00:10:00							1	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/>			00:10:00
7	W side of Parking lot/clubhouse	00:10:00	00:10:00							1	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/>			00:10:00
8	Round about median and w side of Pennington	00:10:00	00:10:00							1	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/>			00:10:00
9	N side of Pennington by Round about	00:10:00	00:10:00							1	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/>			00:10:00
10	S. side of entry round about	00:10:00	00:10:00							1	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/>			00:10:00
11	East side of South entry lake	00:10:00	00:10:00							1	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/>			00:10:00
12	S. side of entry S end of lake	00:10:00	00:10:00							1	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/>			00:10:00
13	S side of entry norht side of lake	00:10:00	00:10:00							1	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/>			00:10:00
14	South side of entry	00:10:00	00:10:00							1	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/>			00:10:00
15	S side pennington W of Round about	00:10:00	00:10:00							1	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/>			00:10:00

Program Report

Site Name: Banyan Bay

Generated on: 01/08/2021 03:12:54 PM

Name: Satellite 001

Description:

Communication:

10.94.16.126:50005

Type: LXD - Direct Satellite

Last Sync Time:

01/08/2021 09:55:52 AM

Seasonal Adjust/ET	Daily Seasonal Adjust
Reference	100%
Current Value	100%

#	Station Name	(A) Program A		(B) Program B		(C) Program C		(D) Program D		FZ	Sensor * 1 2 3	Cycle	Soak	Total Adjusted
		Run Time		Run Time		Run Time		Run Time						
		Base	Adjusted	Base	Adjusted	Base	Adjusted	Base	Adjusted					
16	N side of Pennington Round about to Millbrook	00:10:00	00:10:00							1	☑☑☑☑			00:10:00
17	4853 Millbrook			00:10:00	00:10:00					1	☑☑☑☑			00:10:00
18	N side of Penningtom ROW	00:10:00	00:10:00							1	☑☑☑☑			00:10:00
19	4813-1823 Millbrook			00:10:00	00:10:00					1	☑☑☑☑			00:10:00
20	4803-1793 Millbrook			00:10:00	00:10:00					1	☑☑☑☑			00:10:00
21	4773-4763-4753 Millbrook			00:05:00	00:05:00					1	☑☑☑☑			00:05:00
22	OS Millbrook near 4753	00:10:00	00:10:00							1	☑☑☑☑			00:10:00
23	OS Millbrook	00:10:00	00:10:00							1	☑☑☑☑			00:10:00
24	OS Millbrook	00:10:00	00:10:00							1	☑☑☑☑			00:10:00
25	OS Millbrook and Cul-de-Sac	00:10:00	00:10:00							1	☑☑☑☑			00:10:00
26	4572-4582 Millbrook			00:10:00	00:10:00					1	☑☑☑☑			00:10:00
27	4592-5602-4612 Millbrook			00:10:00	00:10:00					1	☑☑☑☑			00:10:00
28	4612-4622 Millbrook			00:10:00	00:10:00					1	☑☑☑☑			00:10:00
29	4632-4642 Millbrook			00:10:00	00:10:00					1	☑☑☑☑			00:10:00
30	4652-4662 Millbrook			00:10:00	00:10:00					1	☑☑☑☑			00:10:00
31	4672-4682 Millbrook			00:10:00	00:10:00					1	☑☑☑☑			00:10:00
32	Rear behind 4692-4702 Millbrook			00:10:00	00:10:00					1	☑☑☑☑			00:10:00

Program Report

Site Name: Banyan Bay

Generated on: 01/08/2021 03:12:54 PM

Name: Satellite 001

Description:

Communication:

10.94.16.126:50005

Type: LXD - Direct Satellite

Last Sync Time:

01/08/2021 09:55:52 AM

Seasonal Adjust/ET	Daily Seasonal Adjust
Reference	100%
Current Value	100%

#	Station Name	(A) Program A		(B) Program B		(C) Program C		(D) Program D		FZ	Sensor * 1 2 3	Cycle	Soak	Total Adjusted
		Run Time		Run Time		Run Time		Run Time						
		Base	Adjusted	Base	Adjusted	Base	Adjusted	Base	Adjusted					
33	4692-4702 Millbrook			00:10:00	00:10:00					1	☑☑☑☑			00:10:00
34	4712-4722 Millbrook			00:10:00	00:10:00					1	☑☑☑☑			00:10:00
35	4732-4742 Millbrook			00:10:00	00:10:00					1	☑☑☑☑			00:10:00
36	OS between 4742 Millbrook/4674 Briarwood	00:10:00	00:10:00							1	☑☑☑☑			00:10:00
37	4674-4684-4694 Briarwood			00:10:00	00:10:00					1	☑☑☑☑			00:10:00
38	4704-4714 Briarwood			00:10:00	00:10:00					1	☑☑☑☑			00:10:00
39	4724-4734-4744 Briarwood			00:10:00	00:10:00					1	☑☑☑☑			00:10:00
40	4754-4764 Briarwood			00:10:00	00:10:00					1	☑☑☑☑			00:10:00
41	Lake Bank 4774- 4783 Briarwood			00:10:00	00:10:00					1	☑☑☑☑			00:10:00
42	4774-4784 Briarwood			00:10:00	00:10:00					1	☑☑☑☑			00:10:00
43	4794-4793 Briarwood			00:10:00	00:10:00					1	☑☑☑☑			00:10:00
44	4783-4773 Briarwood			00:10:00	00:10:00					1	☑☑☑☑			00:10:00
45	4763-4753-4743 Island Briarwood			00:10:00	00:10:00					1	☑☑☑☑			00:10:00
46	4733-4723-4713 Briarwood			00:10:00	00:10:00					1	☑☑☑☑			00:10:00

Program Report

Site Name: Banyan Bay

Generated on: 01/08/2021 03:12:54 PM

Name: Satellite 001

Description:

Communication:

10.94.16.126:50005

Type: LXD - Direct Satellite

Last Sync Time:

01/08/2021 09:55:52 AM

Seasonal Adjust/ET	Daily Seasonal Adjust
Reference	100%
Current Value	100%

#	Station Name	(A) Program A		(B) Program B		(C) Program C		(D) Program D		FZ	Sensor * 1 2 3	Cycle	Soak	Total Adjusted
		Run Time		Run Time		Run Time		Run Time						
		Base	Adjusted	Base	Adjusted	Base	Adjusted	Base	Adjusted					
47	Lake Bank 4783-4713 Briarwood			00:10:00	00:10:00					1	☑☑☑☑			00:10:00
48	4703-4693 Briarwood			00:10:00	00:10:00					1	☑☑☑☑			00:10:00
49	4802-4812 Millbrook			00:10:00	00:10:00					1	☑☑☑☑			00:10:00
50	4822-4832 Millbrook			00:10:00	00:10:00					1	☑☑☑☑			00:10:00
51	Station 0Cul-de-Sac Island S Millbrook51	00:10:00	00:10:00							1	☑☑☑☑			00:10:00
52	4882-4892 Millbrook			00:10:00	00:10:00					1	☑☑☑☑			00:10:00
53	4862-4872 Millbrook			00:10:00	00:10:00					1	☑☑☑☑			00:10:00
54	4852-Parking Millbrook			00:10:00	00:10:00					1	☑☑☑☑			00:10:00
55	S Side Pnnington from Millbrook to Montclair	00:10:00	00:10:00							1	☑☑☑☑			00:10:00
56	Pennington west of Millbrook	00:10:00	00:10:00							1	☑☑☑☑			00:10:00
57	Pennington ROW 1	00:10:00	00:10:00							1	☑☑☑☑			00:10:00
58	Pennington Section 2	00:10:00	00:10:00							1	☑☑☑☑			00:10:00
59	4863-4873 Montclair cir			00:10:00	00:10:00					1	☑☑☑☑			00:10:00
60	4883-4893 Montclair cir			00:10:00	00:10:00					1	☑☑☑☑			00:10:00
61	cul de sac and os Montclair cir	00:10:00	00:10:00							1	☑☑☑☑			00:10:00

Program Report

Site Name: Banyan Bay

Generated on: 01/08/2021 03:12:54 PM

Name: Satellite 001

Description:

Communication:

10.94.16.126:50005

Type:

LXD - Direct Satellite

Last Sync Time:

01/08/2021 09:55:52 AM

Seasonal Adjust/ET	Daily Seasonal Adjust
Reference	100%
Current Value	100%

#	Station Name	(A) Program A		(B) Program B		(C) Program C		(D) Program D		FZ	Sensor * 1 2 3	Cycle	Soak	Total Adjusted
		Run Time		Run Time		Run Time		Run Time						
		Base	Adjusted	Base	Adjusted	Base	Adjusted	Base	Adjusted					
62	4924-4934 Montclair cir			00:10:00	00:10:00					1	☑☑☑☑			00:10:00
63	4914-4904 Montclair cir			00:10:00	00:10:00					1	☑☑☑☑			00:10:00
64	4894-4884 Montclair Cir			00:10:00	00:10:00					1	☑☑☑☑			00:10:00
65	4874-4864 Montclair cir			00:10:00	00:10:00					1	☑☑☑☑			00:10:00
66	Pennington section 3	00:10:00	00:10:00							1	☑☑☑☑			00:10:00
67	Pennington ROW Sec 2	00:10:00	00:10:00							1	☑☑☑☑			00:10:00
68	Pennington Section 4	00:10:00	00:10:00							1	☑☑☑☑			00:10:00
69	Station 69									1	☑☑☑☑			
70	Station 70									1	☑☑☑☑			
71	Station 71									1	☑☑☑☑			
72	Cul de sac Ardsley	00:10:00	00:10:00							1	☑☑☑☑			00:10:00
73	4821-4811 Ardsley					00:10:00	00:10:00			1	☑☑☑☑			00:10:00
74	Lots 3a-4a-5a					00:10:00	00:10:00			1	☑☑☑☑			00:10:00
75	Lots 6a-7a									1	☑☑☑☑			
76	4741-4751 Ardsley					00:10:00	00:10:00			1	☑☑☑☑			00:10:00
77	Lake bank/ os between lots 9a-10a									1	☑☑☑☑			

Program Report

Site Name: Banyan Bay

Generated on: 01/08/2021 03:12:54 PM

Name: Satellite 001

Description:

Communication:

10.94.16.126:50005

Type: LXD - Direct Satellite

Last Sync Time:

01/08/2021 09:55:52 AM

Seasonal Adjust/ET	Daily Seasonal Adjust
Reference	100%
Current Value	100%

#	Station Name	(A) Program A		(B) Program B		(C) Program C		(D) Program D		FZ	Sensor * 1 2 3	Cycle	Soak	Total Adjusted
		Run Time		Run Time		Run Time		Run Time						
		Base	Adjusted	Base	Adjusted	Base	Adjusted	Base	Adjusted					
78	OS between lots 9a-10a									1	☑☑☑☑			
79	Lots 10a-11a					00:10:00	00:10:00			1	☑☑☑☑			00:10:00
80	4661-4671-4681 Ardsley/lot 14					00:10:00	00:10:00			1	☑☑☑☑			00:10:00
81	4641-4651 Ardsley					00:10:00	00:10:00			1	☑☑☑☑			00:10:00
82	Lake bank behind lot 17									1	☑☑☑☑			
83	4631-4621 Ardsley					00:10:00	00:10:00			1	☑☑☑☑			00:10:00
84	Lake bank behind lot 19									1	☑☑☑☑			
85	Lots 19a-20a									1	☑☑☑☑			
86	4611-4601 Ardsley					00:10:00	00:10:00			1	☑☑☑☑			00:10:00
87	Lots 21a-22a									1	☑☑☑☑			
88	preserve behind lot 22a									1	☑☑☑☑			
89	Lots 23a-24a									1	☑☑☑☑			
90	4610-4620-4630 Ardsley					00:10:00	00:10:00			1	☑☑☑☑			00:10:00
91	4640-4650-4660 Ardsley					00:10:00	00:10:00			1	☑☑☑☑			00:10:00
92	4670-4680-4690 Ardsley					00:10:00	00:10:00			1	☑☑☑☑			00:10:00
93	4700-4710-4720 Ardsley					00:10:00	00:10:00			1	☑☑☑☑			00:10:00

Program Report

Site Name: Banyan Bay

Generated on: 01/08/2021 03:12:54 PM

Name: Satellite 001

Description:

Communication:

10.94.16.126:50005

Type: LXD - Direct Satellite

Last Sync Time:

01/08/2021 09:55:52 AM

Seasonal Adjust/ET	Daily Seasonal Adjust
Reference	100%
Current Value	100%

#	Station Name	(A) Program A		(B) Program B		(C) Program C		(D) Program D		FZ	Sensor * 1 2 3	Cycle	Soak	Total Adjusted
		Run Time		Run Time		Run Time		Run Time						
		Base	Adjusted	Base	Adjusted	Base	Adjusted	Base	Adjusted					
94	4730-4740-4750 Ardsley					00:10:00	00:10:00			1	☑☑☑☑			00:10:00
95	Lake bank behind lot 40									1	☑☑☑☑			
96	Station 096									1	☑☑☑☑			
97	4790-4800 Ardsley					00:10:00	00:10:00			1	☑☑☑☑			00:10:00
98	Lots 40a-41a-42a					00:10:00	00:10:00			1	☑☑☑☑			00:10:00
99	OS corner of Ardsley and Pennington	00:10:00	00:10:00							1	☑☑☑☑			00:10:00
100	Station 100									1	☑☑☑☑			
101	lake bank Ardsley	00:20:00	00:20:00							1	☑☑☑☑			00:20:00
102	Winchester/ Ardsley Round about	00:20:00	00:20:00							1	☑☑☑☑			00:20:00
103	By pump station	00:10:00	00:10:00							1	☑☑☑☑			00:10:00
104	By Lift station									1	☑☑☑☑			
105	West of lift station									1	☑☑☑☑			
106	Rotors across from controller	00:20:00	00:20:00							1	☑☑☑☑			00:20:00
107	ROW across from controller	00:10:00	00:10:00							1	☑☑☑☑			00:10:00
108	Station 108									1	☑☑☑☑			
109	Station 109									1	☑☑☑☑			
110	Lots 45a-46a							00:10:00	00:10:00	1	☑☑☑☑			00:10:00

Program Report

Site Name: Banyan Bay

Generated on: 01/08/2021 03:12:54 PM

Name: Satellite 001

Description:

Communication:

10.94.16.126:50005

Type: LXD - Direct Satellite

Last Sync Time:

01/08/2021 09:55:52 AM

Seasonal Adjust/ET	Daily Seasonal Adjust
Reference	100%
Current Value	100%

#	Station Name	(A) Program A		(B) Program B		(C) Program C		(D) Program D		FZ	Sensor * 1 2 3	Cycle	Soak	Total Adjusted
		Run Time		Run Time		Run Time		Run Time						
		Base	Adjusted	Base	Adjusted	Base	Adjusted	Base	Adjusted					
111	Lots 47a-48a							00:10:00	00:10:00	1	☑☑☑☑			00:10:00
112	Lake Bank behind lot 49a									1	☑☑☑☑			
113	Lots 49a-50a									1	☑☑☑☑			
114	lots 51a-52a							00:10:00	00:10:00	1	☑☑☑☑			00:10:00
115	Lots 53a-54a									1	☑☑☑☑			
116	Lots 55a-56a									1	☑☑☑☑			
117	Lots 57a-58a									1	☑☑☑☑			
118	Lots 59a-60a									1	☑☑☑☑			
119	Lake Bank behind Lot 60a									1	☑☑☑☑			
120	OS next to Lot 60a									1	☑☑☑☑			
121	Cul de sac 2 Pennfield	00:10:00	00:10:00							1	☑☑☑☑			00:10:00
122	Parking area Pennfield									1	☑☑☑☑			
123	Parking area Pennfield									1	☑☑☑☑			
124	Station 124									1	☑☑☑☑			
125	Lots 61a-62a									1	☑☑☑☑			
126	Lots 63a-64a-65a									1	☑☑☑☑			
127	Lots 66a-67a									1	☑☑☑☑			
128	Lots 68a-69a-70a									1	☑☑☑☑			
129	Lots 71a-72a-Island	00:10:00	00:10:00					00:10:00	00:10:00	1	☑☑☑☑			00:20:00

Program Report

Site Name: Banyan Bay

Generated on: 01/08/2021 03:12:54 PM

Name: Satellite 001

Description:

Communication:

10.94.16.126:50005

Type: LXD - Direct Satellite

Last Sync Time:

01/08/2021 09:55:52 AM

Seasonal Adjust/ET	Daily Seasonal Adjust
Reference	100%
Current Value	100%

#	Station Name	(A) Program A		(B) Program B		(C) Program C		(D) Program D		FZ	Sensor * 1 2 3	Cycle	Soak	Total Adjusted
		Run Time		Run Time		Run Time		Run Time						
		Base	Adjusted	Base	Adjusted	Base	Adjusted	Base	Adjusted					
130	Lots 73a-74a					00:10:00	00:10:00	00:10:00	00:10:00	1	☑☑☑☑			00:20:00
131	Lots 75a-76a							00:10:00	00:10:00	1	☑☑☑☑			00:10:00
132	Lots 77a-78a							00:10:00	00:10:00	1	☑☑☑☑			00:10:00
133	Lots 79a-80a									1	☑☑☑☑			
134	Station 134									1	☑☑☑☑			
135	Lots 81a-82a									1	☑☑☑☑			
136	Station 136									1	☑☑☑☑			
137	OS Riverwatch	00:10:00	00:10:00							1	☑☑☑☑			00:10:00
138	OS Riverwatch	00:10:00	00:10:00							1	☑☑☑☑			00:10:00
139	OS Riverwatch South	00:10:00	00:10:00							1	☑☑☑☑			00:10:00
140	Station 140									1	☑☑☑☑			
141	Station 141									1	☑☑☑☑			
142	Station 142									1	☑☑☑☑			
143	Riverwatch Cul de Sac	00:20:00	00:20:00							1	☑☑☑☑			00:20:00
144	Lots 104a-105a									1	☑☑☑☑			
145	Lots 106a-107a									1	☑☑☑☑			
146	Lots 108a-109a									1	☑☑☑☑			
147	Lots 110a-111a									1	☑☑☑☑			
148	Station 148									1	☑☑☑☑			
149	Station 149									1	☑☑☑☑			

Program Report

Site Name: Banyan Bay

Generated on: 01/08/2021 03:12:54 PM

Name: Satellite 001

Description:

Communication:

10.94.16.126:50005

Type:

LXD - Direct Satellite

Last Sync Time:

01/08/2021 09:55:52 AM

Seasonal Adjust/ET	Daily Seasonal Adjust
Reference	100%
Current Value	100%

#	Station Name	(A) Program A		(B) Program B		(C) Program C		(D) Program D		FZ	Sensor * 1 2 3	Cycle	Soak	Total Adjusted
		Run Time		Run Time		Run Time		Run Time						
		Base	Adjusted	Base	Adjusted	Base	Adjusted	Base	Adjusted					
150	Winchester Cul De Sac	00:10:00	00:10:00							1	☑☑☑☑			00:10:00
151	Winchester OS Rotors	00:20:00	00:20:00							1	☑☑☑☑			00:20:00
152	Lots 96a-97a									1	☑☑☑☑			
153	Lots 94a-95a									1	☑☑☑☑			
154	Lots 92a-93a									1	☑☑☑☑			
155	Lots 90a-91a									1	☑☑☑☑			
156	Loake behind 91a									1	☑☑☑☑			
157	Lots 88a-89a									1	☑☑☑☑			
158	Lots 86a-87a									1	☑☑☑☑			
159	OS Behind lot 85a									1	☑☑☑☑			
160	Lots 84a-85a									1	☑☑☑☑			
161	Lot 83a									1	☑☑☑☑			
162	Station 162									1	☑☑☑☑			
163	Station 163									1	☑☑☑☑			
164	Station 164									1	☑☑☑☑			
165	Station 165									1	☑☑☑☑			
166	Station 166									1	☑☑☑☑			
167	Station 167									1	☑☑☑☑			
168	Station 168									1	☑☑☑☑			
169	Station 169									1	☑☑☑☑			

Program Report

Site Name: Banyan Bay

Generated on: 01/08/2021 03:12:54 PM

Name: Satellite 001

Description:

Communication:

10.94.16.126:50005

Type:

LXD - Direct Satellite

Last Sync Time:

01/08/2021 09:55:52 AM

Seasonal Adjust/ET	Daily Seasonal Adjust
Reference	100%
Current Value	100%

#	Station Name	(A) Program A		(B) Program B		(C) Program C		(D) Program D		FZ	Sensor * 1 2 3	Cycle	Soak	Total Adjusted
		Run Time		Run Time		Run Time		Run Time						
		Base	Adjusted	Base	Adjusted	Base	Adjusted	Base	Adjusted					
170	Station 170									1	☑☑☑☑			
171	Station 171									1	☑☑☑☑			
172	Station 172									1	☑☑☑☑			
173	Station 173									1	☑☑☑☑			
174	Station 174									1	☑☑☑☑			
175	Station 175									1	☑☑☑☑			
176	Station 176									1	☑☑☑☑			
177	Station 177									1	☑☑☑☑			
178	Station 178									1	☑☑☑☑			
179	Station 179									1	☑☑☑☑			
180	Station 180									1	☑☑☑☑			
181	Station 181									1	☑☑☑☑			
182	Station 182									1	☑☑☑☑			
183	Station 183									1	☑☑☑☑			
184	Station 184									1	☑☑☑☑			
185	Station 185									1	☑☑☑☑			
186	Station 186									1	☑☑☑☑			
187	Station 187									1	☑☑☑☑			
188	Station 188									1	☑☑☑☑			
189	Station 189									1	☑☑☑☑			
190	Station 190									1	☑☑☑☑			
191	Station 191									1	☑☑☑☑			

Program Report

Site Name: Banyan Bay

Generated on: 01/08/2021 03:12:54 PM

Name: Satellite 001

Description:

Communication:

10.94.16.126:50005

Type: LXD - Direct Satellite

Last Sync Time:

01/08/2021 09:55:52 AM

Seasonal Adjust/ET	Daily Seasonal Adjust
Reference	100%
Current Value	100%

#	Station Name	(A) Program A		(B) Program B		(C) Program C		(D) Program D		FZ	Sensor * 1 2 3	Cycle	Soak	Total Adjusted
		Run Time		Run Time		Run Time		Run Time						
		Base	Adjusted	Base	Adjusted	Base	Adjusted	Base	Adjusted					
192	Station 192									1	☑☑☑☑			
193	Station 193									1	☑☑☑☑			
194	Station 194									1	☑☑☑☑			
195	Station 195									1	☑☑☑☑			
196	Station 196									1	☑☑☑☑			
197	Station 197									1	☑☑☑☑			
198	Station 198									1	☑☑☑☑			
199	Station 199									1	☑☑☑☑			
200	Station 200									1	☑☑☑☑			